



1. Once you provide us with the art for your coins our artist will get to work converting your image to a format that our machines can read for cutting the die. The amount of time this takes depends on the quality of the art you send and the number of orders ahead of yours. You might be asked to provide a vector file to assist the artist in precision and speedy delivery.
2. We will send you the proof and wait for your approval to begin cutting the die.
3. Through a combination of laser cutting and precision sculpting your steel die will be created.
4. The die must then be heat treated or cured. This process involves high heat in a kiln and cooling the die several times to the required specifications. This process takes 48 hours or more to complete.
5. Now is when the coins get struck in a high capacity hydraulic coin press.
6. Once the coins are struck the metal finishing must be applied. The finishing agent is applied and buffed and heat cured.
7. Now the coins must be dried and set. This part of the process takes approximately 2 days.
8. Now your coins are ready to package and ship.

The entire process normally takes several weeks.